

Title:	Plate Slips on Shovel	ID:	
		0348	
Date in:	Response:	Model:	Author:
2010-02-11	2010-02-11		CMa

We have an intermittent problem, please see the video. This predominantly occurs with Costar plates and often on the first one or first few plates of a run.

We have a new type shovel you may consider. This type shovel was made for plates with low wells and/or glass bottom. I added picture.

