

Title:	STX1000 Slide Installation			ID:
				0219
Date in:	Response:	Model:	Author:	
2004-04-05	2004-04-05	STX1000	CMa	

Thanks for the info. Here in lies the problem. I am excited about the performance of the STX 1000 however, the automated access door is on the long side of the store. I cannot afford to give up this much robotic real-estate in order to get the store close enough to the system so the robot can retrieve plates. You should mention this to your applications people and see if they can redesign the store to have automated access on the short side of the store.

